

# Repair Station Operations Specifications

(Continuation)

## Limitations:

The ratings (s) set forth on Air Agency Certificate Number C33R897J is/are limited to the following:

### LIMITED RATINGS:

AIRFRAME: BELL:47,204,205,206,212, OH-13, TH-13, UH-1, HU-1,OH-58 SERIES  
HUGHES MCDONALD DOUGLAS: 269,369, TH-55, OH-6 SERIES  
SCHWIETZER: 269, 300 SERIES  
HILLER: UH-12, OH-23 SERIES

POWERPLANT: OVERHAUL  
LYCOMING 235, 320, 360, 435, 540, T53, SERIES  
CONTINENTAL A65, A75, A95,145 200,300,470,520,SERIES  
FRANKLIN:335,350 SERIES  
ALLISON:250,T63 SERIES

ACCESSORY: OVERHAUL  
TCM (BENDIX MAGNETOS: 20 200,1200 SERIES

THIS AUTHORIZATION IS FURTHER LIMITED TO INSPECTION, REMOVAL/INSTALLATION OF ACCESSORIES AND COMPONENTS, ADJUSTMENTS, MINOR REPAIRS AND MINOR ALTERATIONS TO THOSE POWER PLANTS INSTALLED ON THE AIRCRAFT AUTHORIZED IN THE ASSOCIATED AIRFRAME RATINGS.

WORK TO BE ACCOMPLISHED IN ACCORDANCE WITH THE PRODUCES MANUFACTURER'S CURRENT TECHNICAL DATA, THE CUSTOMER'S AIR CARRIERS MANUAL (FAR 145.2) OR OTHER DATA APPROVED BY THE ADMINISTRATOR.

## Delegated authorities:

Date issued or revised:

FEBRUARY 23, 1995

For the Administrator:



THOMAS L. MILLER

AVIATION SAFETY INSPECTOR,ASO-FSDO-09